

Building Compliance Summary

Horizon Property Management — Demo
Generated 2026-08-20 · Entirely synthetic data

Immeuble Montcalm · 410, rue du Registre, Longueuil

Check valve no. 2 — result outside tolerance — Repair coordination requested

Device	Type	Location	Serial	Status	Last	Next
DAR-0601	RP	Mechanical room B2	HX-2020-08001	Compliant	2026-02-13	2027-06-01
DAR-0602	RP	Mechanical room B1	HX-2020-08002	Action required	2026-02-12	2027-06-01
DAR-0603	DCVA	Mechanical room B2	HX-2020-08003	Action required	2026-02-11	2027-06-01

Recent activity

- 2026-08-15 · Système — Deficiency recorded
- 2026-03-21 · Système — Next due date created
- 2026-07-29 · Marie Tremblay — Démo — Report viewed
- 2026-08-12 · Système — Reminder sent